

Date	Weather	
Wed. /Sep 4	Sunshine	In the evening we noticed there was some moisture in the the vapor barrier beside the basement windows for the first time.
Thu. /Sep 5	Sunshine	Talked with the builder in the morning and the builder replaced the insulation material. Re-checked in the evening, the moisture was gone where the material was replaced, but the moisture was still there for the area not replaced.it looked OK.
Fri. /Sep 6	rain	Talked with the builder in the morning, the moisture was there, but no visit in the evening.
Sat. /Sep 7	rain	Checked in the evening, all moisture was gone.
Sun. /Sep 8	Sunshine	Checked in the evening, the moisture appeared again.
Mon. /Sep 9	Sunshine	Talked with the builder in the morning, the moisture was gone.

