


Current Situation

1960s home, so probably no sill sealer or caulk



Proposed Installation

This is a small modification of a GBA detail.

Termites could potentially come up behind protective covering or the insulation.

